

2022 HAZARD HUNT MILESTONE 3 HAZARD RESOLUTION

KUWAIT DINING FACILITY (DFAC) NORTH OF THE BORDER TEAM REPLACES WEAK FLOORING TO ELIMINATE ACCIDENTS



It became apparent quickly that the flooring in the Camp Buehring commercial kitchen could not withstand the heavy load it was expected to endure. New steel checker plate flooring was selected and because the kitchen provides meals to our Warfighters and contractors almost continuously, Phase I of the work took place between midnight and 3:00 a.m. The finished product is much more appropriate for the work load and this replacement earned the North of the Border team **a finalist position in the 2021 Hazard Hunt!**

FOR **MILESTONE 3 – HAZARD RESOLUTION**, TEAMS SHOULD:

- Demonstrate how you resolved the hazard.
- Take a video or photos of the hazard after it is resolved. Make sure the photo file sizes are each 1MB or larger and include people. Ensure each individual included in photos signs an [Image Release Form](#) found on the [Hazard Hunt web page](#).
- Write a summary with the who, what, when, where, and how you resolved the safety, occupational health, or environmental hazard.